







Измерение давления




5





5



8



6



Aereco S.A.

9 allée du Clos des Charmes - Collégien
77615 Marne la Vallée Cdx 3 - FRANCE
tel: +33 1 60 06 26 63 - fax: +33 1 60 06 22 11
www.aereco.com

2

Ø3,5 x 35 мм

3

Ø100 мм Ø100 - Ø100 мм

Ø125 мм Ø125 - Ø100 мм

1

Ø100 - Ø125 мм

5

6

7

8

Ø3,5 x 35 мм

9

Установка расхода воздуха

позиция 2

позиция 1

Ø 100 мм

Расход воздуха (м³/ч) при 100 Па		позиция 2		
		A	B	C
позиция 1	0	12	50	80
	1	18	55	90
	2	24	60	100
	3	30	70	110
	4	36	80	120
	5	42	90	130

Ø 125 мм

Расход воздуха (м³/ч) при 100 Па		позиция 2		
		A	B	C
позиция 1	0	12	50	70
	1	18	55	80
	2	24	60	90
	3	30	70	100
	4	36	75	110
	5	42	80	120

позиция 1

позиция 2

1

2

3

4

5

6

A **B** **C**

7

8